# Kensington®

Windows 11 Setup Guide for VeriMark™ Guard

1. Click on **Start** on the taskbar and **click** on **Settings**

2. Click on **Accounts** to show sign in options.

3. Click on **Sign-in** options


4. Alternatively, you can **click** on the **magnifier glass** on the taskbar and **search** for **"Set up security key"**

**5.** Click on **Security Key** and **Manage**

6. Under Manage **touch** the **USB dongle** to access features


7. If it is the first time using a security key, you need to add a **security PIN**.
Click on **add** under Security Key

**8.** Enter a security key **PIN** then click **OK** for next step

9. Once PIN has been entered **Set Up fingerprint** on the following window

10. Enter PIN previously set up and click **OK** to proceed

**11.** Touch the fingerprint sensor area **repeatedly**

**12.** Enter **PIN** previously set up and click **OK** to proceed

13. Click **Done** to finish fingerprint enrollment **or Add another finger** to set up another fingerprint

14. On the main window you can also **add another fingerprint** or **remove** the fingerprint as well as **change the PIN**


15. To reset the USB dongle and erase all the fingerprints click on **Reset Security Key**

16. Click **proceed** and follow the instructions to **reset** the USB dongle

17. Disconnect and reconnect the USB dongle

18. **Touch** the security key twice

19. Click **done** to finish reset

Kensington®